



FAG

XCS71926-E-T-P4S-UL

Высокоскоростной шпиндельный подшипник

High speed spindle bearing XCS719..-E, adjusted, in pairs or sets, contact angle $\alpha = 25^\circ$, with ceramic balls, with Cronidur rings, lip seals on both sides, non-contact, restricted tolerances

Техническая информация
