



IMAGE
COMING SOON

FAG

XCS71926-E-T-P4S-UL

Высокоскоростной шпиндельный подшипник

High speed spindle bearing XCS719..-E,
adjusted, in pairs or sets, contact angle $\alpha = 25^\circ$, with ceramic balls, with Cronidur rings,
lip seals on both sides, non-contact, restricted tolerances

Техническая информация
